

FIG. 1




FIG. 1




FIG. 3




FIG. 2

FOOT T302000T




Fig. 4




Fig. 5




FIG. 6




FIG. 9

FIG. 7





FIG. 8











Fig. 13





170




FIG. 20

FIG. 18





FIG. 19




FIG. 21




FIG. 22A




FIG. 22B

FIG. 22B




FIG. 23

FIG. 24A




FIG. 24B




FIG. 24C





FIG. 24D









FIG. 26

FIG. 25




FIG. 29




FIG. 30




FIG 31




FIG. 32

10007064-43004
100211902000

10007061-13001




FIG. 33

FIG. 34




FIG. 35




FIG. 38




FIG. 36




FIG. 37





FIG. 34

100070001

Pressure



Time

Fig. 39

FOOT-1000000

Pressure





FIG. 40

Time

FOOT - 1000000

Pressure



Time

FIG. 41

FOOT-F902000F

Pressure




Fig. 42

Time

Pressure
FOOT = 1902000





FIG. 43

TOGETT T502000T

Pressure




Time

FIG. 44

10007051-1300000

Pressure



Time

FIG. 45

Pressure




FIG 46

Pressure





FIG. 47

Time

FOOT-TSODT

Pressure



Time

FIG. 48

Pressure




FIG. 49

Time

10007061-113004

Pressure




FIG. 50

Time

FOOT-F300000

Pressure




FIG. 51

Time

10067051 10067051 10067051

Pressure




FIG. 52

Time

10007061-113004

Pressure




FIG 53

Time

Pressure




FIG. 54

Time